



### SCHEMATIC



### WIRING DIAGRAM



#### NOTE:

• POSITIVE BRUSH CLOSEST TO BEARING