



SURPLUS CENTER

1015 West "O" Street • P.O. Box 82209 • Lincoln, NE 68501-2209
1-800-488-3407 • FAX 402-474-5198 • www.surpluscenter.com



11-1914



Upon application of 24 Volts AC to terminals 4 and 5, the load is energized and a time delay is initiated. On completion of the delay period, the load is de-energized. 24 Volts AC must be applied to terminals 4 and 5 for the load to receive voltage.