





**Use template to line up gearbox shaft and mounting hole.
Hold against mounting surface and mark holes before drilling.**

For best results when printing this PDF, set the page scaling to 'NONE' to insure the dimension are the correct size.



Gearbox

**12 Volt
Motor**



**CAUTION!
IMPORTANT:**

5541095 gear motor must be used with a minimum 50 Amp or 60 Amp in-line circuit breaker between battery and switch. When replacing a Roll-Rite™ #1031 tarp master motor, its 30 Amp circuit breaker must be replaced with a 50 Amp or 60 Amp circuit breaker.

**CAUTION!
IMPORTANT:**

Apply blue medium/high strength thread-locker to gear motor and chrome cover mounting screws.

* Fits common 3-Bolt and 4-Bolt gear motor mounts

